



Adhesion problem - Polyester putty

Description

Loss of adhesion between the substrate and PE putty.

Cause

- Substrate not properly prepared and degreased;
- Uncured putty - too little or too much hardener;

Prevention

- Sand and degrease substrate properly;
- Add recommended quantity of hardener;
- Ensure that the hardener is thoroughly mixed;

Rectification

- Sand, degrease the damaged area and apply PE putty.