



Overspray (Fuzz, Hazing, Poor melt in)

Description

Spray dust deposited on the surface. Paint particles adhering to the paint film or partially absorbed in the surface of the paint film.

Cause

- Paint from a subsequent application sets on the surface;
- Wrong masking;
- Air pressure too high;
- Inadequate extraction or ventilation;

Prevention

- Protect adjacent surfaces from spray dust and mask the surfaces carefully;
- Set up spray gun properly;
- Ensure correct air circulation and extraction in spray booth;

Rectification

- Flat, compound and polish.