



Hiding (Coverage, Opacity, Transparency)

Description

- The undercoat is visible on the repaired area through the topcoat.

Cause

- Too much thinner used;
- Insufficient thickness of the paint film;
- Paint not mixed and/or stirred well;
- Improper spraying technique;
- Inadequate lighting in the spray booth;

Prevention

- Use recommended thinner;
- Mix and stir paint thoroughly;
- Spray sufficient paint to reach opacity;
- Use the appropriate shade of filler;

Rectification

- Sand the affected area and repaint.