



Chipping (Stone chipping, Chipped paints)

Description

Damaged topcoat, small chips of topcoat losing adhesion from surfaces caused by impact of stones, hard and sharp objects.

Cause

- Stones, hard and sharp objects hit vehicle topcoat under speed on the road.

Prevention

- Use a flexibilized filler or surfacer within the refinish system. Pay attention to front of hood, lower side areas and around wheel openings;
- Care should be taken to protect vehicles in transit;

Rectification

- Sand the affected area, apply putty and refinish.