



### **Blushing** (Blooming, Color change)

#### **Description**

A milky white deposit or bloom formed on the paint film.

#### **Cause**

- Spraying during cold or humid weather. Moisture vapor condensing forms tiny droplets of water and being trapped in the wet film;
- Use of too fast thinner;
- Use of poor quality thinner;
- Drafts or fanning air over surface;

#### **Prevention**

- Avoid spraying in extreme conditions, i.e. during rainy, cold or humid weather;
- Use the proper grade of thinner;
- Allow solvent release to take place naturally;
- Allow car parts, paints and room to reach normal temperature;

#### **Rectification**

- In most cases flattening and repainting is needed;